

	Type	L #	Hits	Search Text
1	BRS	L1	93	"5600350"
2	BRS	L2	85	"5635969"
3	BRS	L16	103	(inoperat\$3 malfunction\$3 fail\$4 bad defect\$3) near3 nozzle same (detect\$3 sens\$3 photosens\$3) with line
4	BRS	L17	0	fixer and 16
5	BRS	L18	46025	(enhanc\$ fixer immoboliz\$3 precurs\$3) near3 (liquid\$3 fluid\$3 clear\$3 colorless)
6	BRS	L19	1	16 and 18
7	BRS	L20	2031	347/19.ccls.
8	BRS	L21	36	16 and 20
9	BRS	L22	113022	((optical adj detect\$3) sens\$3 photodetect\$3 discriminat\$3) near3 line
10	BRS	L23	49	16 and 22

	DBs	Time Stamp	Comments
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 09:45	
2	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 11:57	
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:00	
4	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:01	
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:06	
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:07	
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:08	
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:10	
9	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:13	
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:13	

	Type	Ref #	Hits	Search Text
93	BRS	S93	61015	"347"/\$.ccls.clm.
94	BRS	S94	48	S92 and S93
95	BRS	S95	2	"6378976"
96	BRS	S96	2	"20010038399"
97	BRS	S97	9	"6312082"
98	BRS	S98	85	"5635969"
99	BRS	S99	253	(dyeless colorless clear) adj3 (fluid\$4 liquid\$3 fixer) and inkjet
100	BRS	S100	2065	347/15,21,95,98,84.cccls.
101	BRS	S101	8569	test adj2 (pattern indicia) same (sens\$3 detect\$3 calibrat\$3 align\$4)
102	BRS	S102	4	S99 and S100 and S101
103	BRS	S103	93	"5600350"
104	BRS	S104	85	"5635969"
105	BRS	S105	103	(inoperat\$3 malfunction\$3 fail\$4 bad defect\$3) near3 nozzle same (detect\$3 sens\$3 photosens\$3) with line
106	BRS	S106	0	fixer and S105
107	BRS	S107	46025	(enhanc\$ fixer immobiliz\$3 precurs\$3) near3 (liquid\$3 fluid\$3 clear\$3 colorless)
108	BRS	S108	1	S105 and S107
109	BRS	S109	2031	347/19.cccls.
110	BRS	S110	36	S105 and S109
111	BRS	S111	113022	((optical adj detect\$3) sens\$3 photodetect\$3 discriminat\$3) near3 line
112	BRS	S112	49	S105 and S111
113	BRS	S113	1	S107 and S112

	DBs	Time Stamp	Comments	Error Definition
93	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/09 15:06		
94	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/09 17:14		
95	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/09 17:17		
96	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 09:52		
97	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 09:56		
98	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 10:13		
99	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 10:15		
100	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 10:17		
101	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/10 10:20		
102	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 09:43		
103	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 09:45		
104	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 11:57		
105	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:00		
106	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:01		
107	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:06		
108	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:07		
109	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:08		
110	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:10		
111	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:13		
112	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:13		
113	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/08/11 12:18		